IN THE UNITED STATES DISTRICT COURT FOR THE MIDDLE DISTRICT OF ALABAMA, NORTHERN DIVISION

DONALD BELL; KATRINA BELL,

Plaintiffs.

v. Civil Action No. 2:05-cv-658-M

TRAVELERS PROPERTY CASUALTY * INSURANCE COMPANY,

Defendants.

AFFIDAYIT OF JEFF SCHOFIELD

"My name is Jeff Schofield and I am over the age of nineteen (19), and have personal knowledge of the following:

I am the owner of Schofield Contracting. After Hurricane Ivan. Don and Katrina Bell contacted me to assess the damage to their home located at 9030 County Road 59, Pine Apple, Alabama, 36471. On October 14, 2004, I inspected the 030 County Road 59. Pine Apple, Alabama, 36471 property. My assessment was limited to an estimate for repair of the home located on this property.

Attached to my affidavit as Exhibit "A" is a true and correct copy of the estimate to repair the home of Don and Katrina Bell given on October 14, 2004. This report is a business record maintained in the ordinary course of business and it accurately reflects my assessment of the subject property.

The foregoing is true and accurate to the best of my knowledge."



Sept Schofield

STATE OF: ALABAMA)

COUNTY OF: Crershaw)

I, the undersigned Notary Public in and for the State of Alabama at Large, hereby certify that the person that signed the foregoing, and who is known to me and who being by me first duly sworn, acknowledged before me on this day that being informed of the contents of the said document, they executed the same voluntarily on the day the same bears date.

SWORN to and SUBSCRIBED before me this the 3rd day of Much , 2006.

My Commission Expires:____

LAY COMMISSION EXPIRES DEC. 28, 2005

Case 2:05-cv-00658-MH**Sylvofield**m (nontracting) 6/2006 Page 3 of 15 P. O. Box 421

P. O. Box 421 Luverne, Alabama 36049 (334) 670-2074 (334) 235-3575

Date: 10-14-04	Bid #SC:
Customer Name: Don Bell Address: 9030 County Road 59 FURMAN, AL 36741	

Job Description	Cost	Total
The following is a bid to repair damage as a Result of Hurricane Ivan to Don Bell's home located at		
of Hurricane Ivan to Don Bell's home located at		
1030 Co. Rd. 59 Furman, AL 36741. The bid includes		
labor and material. Please see the following pages for an itemization of labor and material.		
For an itemization of labor and material.		
	•	
		EXHIBIT
	16 biles	A
1 September 1	- 3	7 9
TOTAL COST	Serence	0 00

<u>Dwelling</u>		Other Structure	<u>es</u>
Paint outside	6,850.00	Dozier Work	3,000.00
Foundation	6,500.00	Fill Dirt	5,200.00
Roof	4,900.00	Drive way	3,600.00
Window	3,600.00	Rift Raft	2,000.00
Floors	8,700.00	Tree Removal	3,600.00
Installation	4,200.00		\$17,400.00
Wiring	3,600.00		
Lights	2,600.00		
Paint inside	5,600.00		
Fireplaces	1,800.00		
Labor	36,000.00		
Materials	74,000.00		
Mildew Clean-up	2,400.00		
Landscaping	7,500.00		
	\$168,250.00		

Total \$185,250.00

Dwelling Detail Sheet


- 1. Foundation- \$6,500.00
 - *re-level house and check piers and beams
- 2. Roof-\$4.900.00 (materials and labor)
 - *take off existing roof and put on new
- 3. Windows and Doors-\$3,600.00
 - *re-align after leveling house (27 windows & 17 doors)
- 4. Insulation-\$4,200.00 (materials and labor)
 - * take out existing insulation in attic & under house and replace.
- 5. Wiring-\$3,600.00
 - *check all wiring in house due to re-leveling of house and check lights.
- 6. Lights-\$2,600.00 (damaged fixtures)
 - *Dining room & Parlor lights replaced
- 7. Paint (inside labor) \$5,600.00 (see rooms detail sheets)
- 8. Fireplaces-\$1,800.00 (see rooms detail sheets)
- 9. Mildew Clean-up- \$2,400.00 (upstairs and in attic)
- 10. Landscaping- \$7,500.00
 - *remove damaged landscaping & replace (includes material, planting & labor)
- 11. Paint outside of house-\$6,850.00 (material & labor)
 - 5960 sq. [†]
 - 68 gals @ \$30.00 = \$2040.00
 - Caulk 8 cases @ 24.00= \$192.00
 - Labor \$4,618.00 includes washing- primer & 3 top coats- plus replace 8 boards damaged by cracking/splitting)

Total-- \$168,250.00

Other Structures <u>Detail Sheet</u>

- 1. <u>Dozier Work-</u> \$3,000.00 (43 hrs @ 70.00/ hour rate)
- 2. Fill Dirt- \$5,200.00 (35 loads @ \$150.00/load)
 *To repair run off damage around structures
- 1. <u>Drive Way</u>- \$3,600.00 (material & labor) run off damage *4 loads of top coat @\$500.00/load= \$2,000.00 plus
 - *6 loads clay @ \$150.00/load= \$900.00 plus
 - 10.5 hrs of tractor work @\$65/hr = \$700.00
 - *Total= \$3,600.00
- 2. Rift Raft- \$2,000.00
 - *4 loads @\$500.00 a load= \$2,000.00
 - *Rift Raft is to hold run off damaged area after repaired
- 3. <u>Tree removal</u> \$3,600.00
 - *to cut and remove all damaged trees

Total-\$17,400.00



	Wood	Surface	Material	Wood
Item	Surface	Damaged	Cost	<u>Labor</u>
Floor	351 sq'	351 sq'	\$6,318.00	
Wall	750 sq '	525 sq'	\$9,450.00	ĺ
Ceiling	<u>351 sq'</u>	<u>351 sq'</u>	<u>\$6,318.00</u>	<u>\$5,143.00</u>
·	1452 sq'	1227 sq'	\$22,086.00	\$5, 143.00

^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')


^{*}Paint- 12 gals @ \$32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint- \$800.00 (Primer & 3 top coats)

^{*}Fireplace- Re-point (outside and inside) \$900.00 (labor & materials)

^{*}Labor to re-finish floor \$3.62 sq' X 351 sq'= \$1,270.62





	Wood	Surface	Material	Wood
Item	Surface	Damaged	Cost	<u>i</u> labor
Floor	351 sq'	**************************************		
Wall	750 sq '		100-100-00-00-0	
Ceiling	<u>351 sq'</u>	<u>30 sq'</u>	<u>\$542.00</u>	\$1,080.00
	1452 sq'	30 sq'	\$542.00	\$1,080.00


^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint- 12 gals @ \$32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint-\$800.00 (Primer & 3 top coats)

^{*}Fireplace- Re-point (outside and inside) \$900.00 (labor & materials)

^{*}Labor to re-finish floor \$3.62 sq' X 351 sq'= \$1,270.62



Item	Wood Surface	Surface Damaged	Material Cost	Wood Labor
Floor	280 sq'		***	<u> </u>
Wall	960 sq '	30 sq'	\$540.00	\$1,080.00
Ceiling	<u>280 sq'</u>	<u>30 sq'</u>	\$540.00	\$1,080.00
	1520 sq'	60 sq'	\$1,080.00	\$2,160.00


^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint- 12 gals @ 32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint- \$800.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 280 sq'= \$1,013.60






	Wood	Surface	Material	Wood
Item	Surface	Damaged	Cost	Labor
Floor	180 sq'	40 sq'	\$720.00	#*** P. ********************************
Wall	560 sq '	20 sq'	\$360.00	armiring-y-passangs
Ceiling	<u>180 sq'</u>	<u>100 sq'</u>	\$1,800.00	\$5,760.00
	920 sq'	160 sq'	\$2,880.00	\$5,760.00

^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint-6 gals @ 32.00 = \$192.00 (primer & 3 top coats)

^{*} Labor to paint- \$400.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 180 sq'= \$651.60




ltem	Wood Surface	Surface Damaged	Material Cost	Wood Labor
Floor	180 sq'	==	www.nu.uu	
Wall	560 sg '	With which had?	Alby Burnishophy	We'redica, des
Ceiling	180 sg'	Silvers worker	******	


^{*} Floor- Heartpine

^{*}Paint- 6 gals @ \$32.00 = \$192.00 (primer & 3 top coats)

^{*} Labor to paint- \$400.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 180 sq'= \$651.60





Item	Wood Surface	Surface Damaged	Material Cost	Wood Labor
Floor	180 sq'			- (MANAGEM 1970)
Wall	760 sq '		enter afferingence.	
Ceiling	180 sq'	4946-1956-04444 v.	3-11-1-11-11-11-11-11-11-11-11-11-11-11-	


^{*} Floor- Heartpine

^{*}Paint- 6 gals @ \$32.00 = \$192.00 (primer & 3 top coats)

^{*} Labor to paint- \$400.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 180 sq'= \$651.60

Hall (Upstairs)



Item	Wood Surface	Surface Damaged	Material Cost	Wood Labor
Floor	180 sq'			
Wall	740 sg '	60 sq'	\$1,080.00	\$2,160.00
Ceiling	180 sq'	180 sg'	\$3,240.00	\$6,480.00
	1100 sa'	240 sa'	\$4,320.00	\$7,508.00


^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint- 12 gals @ 32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint- \$800.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 180 sq'= \$651.60

<u>Upstairs Bedroom-Right side (coming up stairs)</u>



	Wood	Surface	Material	Wood
Item	Surface	Damaged	Cost	Labor
Floor	351 sq'	351 sq'	\$6,318.00	*************
Wall	750 sq '	525 sq'	\$9,450.00	- manus-reputation
Ceiling	<u>351 sa'</u>	<u>351 sq'</u>	\$6,318.00	<u>\$5,143.00</u>
	1452 sq'	1227 sq'	\$22,086.00	\$5 143.00


^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint- 12 gals @ 32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint- \$800.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 351 sq'= \$1,270.62

Upstairs Bedroom-Left side (coming up stairs)



Item	Wood Surface	Surface Damaged	Material Cost	Wood Labor
Floor	351 sq'	351 sq'	\$6,318.00	***************************************
Wall	750 sq '	525 sq'	\$9,450.00	
Ceiling	<u>351 sqʻ</u>	<u>351 sgʻ</u>	\$6,318.00	\$5 143.00

1227 sq'

\$22,086.00

\$5,143.00

1452 sq'

^{*} Wood- Heartpine @ \$18.00 sq ' (1 1/4" X 6"X 20')

^{*}Paint- 12 gals @ 32.00 = \$408.00 (primer & 3 top coats)

^{*} Labor to paint- \$800.00 (Primer & 3 top coats)

^{*}Labor to re-finish floor \$3.62 sq' X 351 sq'= \$1,270.62